

## Katunayake Maintenance - Support #1369

### Generation of transparent cover

02/21/2019 07:11 AM - Letchuman Dineshkumar

<b>Status:</b>	New	<b>Start date:</b>	02/21/2019
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Letchuman Dineshkumar	<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Description</b>			
wrong amount of transparent cover for busbar connection generation in BOM for insulated bus bar system			